



Plasma Welding Gas Manifold

Argon Gas Supply.
Line pressure higher than 40PSI.

Welding Gas Pressure Line
Regulators set to 40PSI.





Dissimilar Plasma Welding Gas Manifold

Argon Gas Supply.
Line pressure higher than 40PSI.

Welding Gas Pressure Line
Regulators set to 40PSI.

Shield Gas Supply (Other than Argon).
Line pressure higher than 40PSI.



Plasma Welding with Cylinder Gas

