

400M/MP TIG, STICK, CAG Easy Find Guide - Build your own Package.

Ordering Information	
ID-4000C-U1E	400M
ID-4000CP-U1E	400MP
MS1102	Running Gear

**Gas Tungsten Arc Welding**



**TIG Torch Kit Air Cooled**

Part No.	Description
TK1006	12.5ft. 17V Style
TK1007	25ft. 17V Style

**Gas Regulator**

Part No.	Description
MS1001	Argon Regulator/Flowmeter


**Work Lead**

Part No.	Description
WCE0006	15ft. Work Lead
WCE0008-25	25ft Work Lead

**Remote Control Device**

Part No.	Description
FC1000	15ft. Foot Control
FC1001	25ft. Foot Control
RC1000	15ft. Remote TIG Torch On/OFF and current cotrol. (Velcro)
RC1001	25ft. Remote TIG Torch On/OFF and current cotrol. (Velcro)
RC1002	15ft. Remote TIG Torch On/OFF. (Velcro)

**Shielded Metal Arc Welding**



**Electrode Lead**

Part No.	Description
WCG0008	15ft. Electrode Lead
WCG0008-25	25ft. Electrode Lead

**Work Lead**

Part No.	Description
WCE0008	15ft. Work Lead
WCE0008-25	25ft. Work Lead

**Remote Control Device**

Part No.	Description
HP1425	25ft. Hand Pendant

**Carbon Arc Gouging**



**Gouging Torch**

Part No.	Description
MS1107	26ft. 600Amp. Gouging Torch

**Work Lead**

Part No.	Description
WCE0008	15ft. Worj Lead
WCE0008-25	25ft. Work Lead

**Remote Control Device**

Part No.	Description
HP1425	25ft. Hand Pendant

## 400M/MP Easy Find Guide - Build your own Package.

Ordering Information	
ID-400C-U1E	400M
ID-400CP-U1E	400MP
MS1102	Running Gear

**Gas Metal Arc Welding**  
**Flux Cored Arc Welding**



### Sky 4HD Wire Feeder

Part No.	Description
WF1300T	Tweco Gun Plug
WF1300M	Miller Gun Plug
WF1300E	Euro Gun Plug
WF-130TPPI	Binzel Push-Pull (Used with MGT2842921)

### MIG Gun

Part No.	Description
MGM45015-3545F	450A, 15ft. Miller Spraymaster Style.
MGT45015T-3545	450A, 15ft. Tweco Spraymaster Style.
MGE35012-35	350A, 12ft. Euro Spraymaster Style.
MGT2842921	25ft. Binzel Push-Pull (Used with WF130TPPI Wire Feeder)

### Interconnection Cable (Coax)

Part No.	Description
WFC004	Wire Feeder Connection coax cable 4 foot
<b>WFC008</b>	<b>Wire Feeder Connection coax cable 8 foot (Best fit with Running Gear)</b>
WFC015	Wire Feeder Connection coax cable 15 foot
WFC025	Wire Feeder Connection coax cable 25 foot
WFC050	Wire Feeder Connection coax cable 50 foot

### Gas Regulator

Part Number	Description
MS1001	Argon Regulator/Flowmeter


### Work Lead

Part Number	Description
WCE0006	15ft. Work Lead
WCE0008-25	25ft. Work Lead

### Common Pre-configured system packages

400M-MK2	Includes 400M, Sky 4HD wire feeder (EURO), 350 amp 12ft. MIG Gun Pkg.
400M-HDMK1T	Includes 400M, Sky 4HD wire feeder (TWECO), 450 amp 15ft. MIG Gun Pkg.
400M-HDMK1TA	Includes 400M, Sky 4HD wire feeder (TWECO) Pkg. (No MIG Gun Included).
400M-HDMK1M	Includes 400M, Sky 4HD wire feeder (Miller) Pkg. (No MIG Gun Included).
400M-Python	Includes 400M Running Gear. MK Python MIG Gun Not Included.
400M-BinzelPPI	Includes 400M, Sky 4HD, Binzel PPI 25ft. RG, Pkg.
400MP-MK2	Includes 400MP, Sky 4HD (EURO) wire feeder, 350, amp 12ft. MIG GUN Pkg..
400MP-HDMK1T	Includes 400MP, Sky 8HD wire feeder, Tweco Style 450 amp 15ft. MIG Gun Pkg.
400MP-HDMK1TA	Includes 400MP, Sky 4HD wire feeder (TWECO) Pkg. No MIG Gun Included.
400MP-HDMK1M	Includes 400MP, Sky 4HD wire feeder, (Miller). No MIG Gun Included.
400MP-Python	Includes 400MP Pkg. MK Python Not Included.
400MP-PPI	Includes 400MP, Sky 4HD wire feeder, Binzel PPI 25ft. Pkg.

## Plasma Arc Welding Handheld Configuration



Part No.	Description
IDU-W150PW-U1DVP	150PW
MS1105	Running Gear/Cylinder Rack



### Plasma Welding Torch (Hand Held)

Part No.	Description
P75-1000	2A - Torch, 70 degree, 12.5ft
P75-1001	2A - Torch, 70 degree, 25ft
P75-1002	2A - Torch, 90 degree, 12.5ft
P75-1003	2A - Torch, 90 degree, 25ft
P15-1000	3A - Torch, 70 degree, 12.5ft
P15-1001	3A - Torch, 70 degree, 25ft
P15-1002	3A - Torch, 90 degree, 12.5ft
P15-1003	3A - Torch, 90 degree, 25ft
P22-1000	4A - Torch, 70 degree, 12.5ft (Includes Torch Head Liner)
P22-1001	4A - Torch, 70 degree, 25ft (Includes Torch Head Liner)
P22-1002	4A - Torch, 90 degree, 12.5ft (Includes Torch Head Liner)
P22-1003	4A - Torch, 90 degree, 25ft (Includes Torch Head Liner)



### Torch Consumables Kit

Part No.	Description
P75-2000	P75 Torch Kit
P15-2000	P15 Torch Kit
P22-2000	P22 Torch Kit



### Gas Regulators (Two Required)

Part No.	Description
MS1005	Argon Regulator (Plasma Welding)
MS1006	Argon/Hydrogen Regulator (Plasma Welding)



### Gas Hose (Two Required)

Part Number	Description
MS1000	12.5ft. Gas Hose.



### Work Lead

Part Number	Description
WCE0006	15ft. Work Lead
WCE0008-25	25ft. Work Lead



### Remote Controls

Part Number	Description
FC1000	15ft. Foot Control
FC1001	25ft. Foot Control
RC1000	15ft. Remote TIG Torch On/OFF and current cotrol. (Velcro)
RC1001	25ft. Remote TIG Torch On/OFF and current cotrol. (Velcro)
RC1002	15ft. Remote TIG Torch On/OF. (Velcro)

